

DIGITAL CLAMP METER M266



This is a 3½ Digits 1000Amp. AC Clamp Meter with AC/DC Voltage, Resistance etc.

SPECIFICATION

Basic Function	Range	Best Accuracy
AC Current	200A/1000A(2 Ranges)	±2%
AC Voltage	750V(Auto Range)	±1%
DC Voltage	1000V(Auto Range)	±0.8%
Resistance	200Ω/20kΩ(2 Ranges)	±1%
Continuity	Yes	

FEATURES

- Display: 3½ Digits with 1999 Counts.
- Data Hold Function all Ranges
- Low Battery Indication
- Overload protection
- Over Range Indication
- Power supply: 9Volt battery
- Clamp Jaw Opening: 51mm.
- Reading Rate: 3 Times/second
- Operating Temperature & Humidity: 0°C To 50°C, <80%RH
- Storage Temperature & Humidity: -20°C To 60°C, <80%RH
- Display Size: 52 x 24mm
- Unit Size: 230×90×34mm

 Weight: 290gm Including Batteries Accessories: Instruction Manual, 1 Set Test Leads, 9 Volt Batteries, Carrying Cover. 			
ean Rooms Pharma Hospital HVAC BulkDrugs Chemicals Heavy Machinery Hydraulics Vacuum Indust Green House Server Room Confined Space Cold Storage	гy		

Instrukart Holdings

INSTRUKART
YOUR WORLDWIDE INSTRUMENT PARTN