


INDOOR AIR QUALITY MONITOR



Combo CO2 & CO & TEMP. Logger w/o humidity: 77596 w/ humidity: 77597

- Upgraded to meet EN 50543:2011 requirement
- Portable meter to check/record indoor air quality: CO₂, CO, temperature, humidity, dew point & wet bulb
- Designed with high accuracy NDIR (non-dispersive infrared) waveguide technology CO₂ sensor
- Designed with fast response electrochemical CO sensor
- Manual calibration is available for CO₂/CO/RH%
- 32000 or 24000 logging memory for #77597 and #77596
- Manual pressure compensation for CO₂ sensor



Model	77597	77596
Measuring range		
CO ₂	0~9999 ppm,	0~9999 ppm,
CO	0~1000 ppm,	0~1000 ppm,
Temperature	-20~60°C (-5~140°F)	
Relative Humidity	0.1%~99.9%RH	N/A
DP(Dew point temp.)	-20.0~59.9°C	N/A
WB(Wet bulb temp.)	-5.0~59.9°C	N/A
Resolution	1ppm , 0.1°C/°F, 0.1%RH	
Accuracy		
CO ₂	±30ppm±5% of reading (0~5000ppm) Other range is 10% of reading	
CO	+/-3 ppm ≤20ppm, +/-5 ppm ≤100ppm +/-10% or reading for 101~500 ppm +/-20% of reading for 501ppm and above	
Temperature	±0.6°C/±0.9°F	
Relative Humidity	±3%RH (at 25°C, 10~90%RH) ; ±5%RH (at 25°C , other range)	
CO ₂ Warm-up time	30 seconds	
Response time		
CO ₂	<30 seconds(90% step change)	
CO	<60 seconds(90% step change)	
Tair	<2 mins (90% step change)	
RH	<10 minutes (90% step change)	
LCD / Meter size (mm)	26(H)x44(L), 205(L)x70(W)x56(H)	
Operating condition	-20 to 50 °C (CO ₂ sensor), 0 to 50 °C (CO sensor) (avoid condensation) -20 to 60 °C (for the rest parameters)	
Storage condition	-20~ 60°C, 10~90%RH(avoid condensation)	
Power supply	AA x 4pcs or 9V adaptor	
Battery life	> 24 hours (Alkaline battery)	
IP Rating	IP40	
EMC	EN 50270:2015	
Weight	200g	
Standard package	Meter, manual ,AA bat. , USB cable & CD, carry case	

Optional



CAL. SALT BOTTLE
P/N: VZ0033AZ1(33%)
P/N: VZ0075AZ1(75%)
FOR 77597
CALIBRATION USE



9V UNIVERSAL ADAPTOR
P/N: VZ109BAZ
100~240VAC INPUT
9V OUTPUT
for 77597/77596

Ordering Code

VZ77597AZ, 77597 logger
VZ77596AZ, 77596 logger
VZ109BAZ, 9V universal adaptor
VZ0033AZ1+VZ0075AZ1, RH calibration



Included!

Temp | Humidity | Pressure | Differential Pressure | Vacuum | Gases | Particle | Air Flow
Moisture | Dissolved Oxygen | Radiation | Air Quality | Light / Lux | Distance | Vibration

Instrukart Holdings

Ph : +91 (40)40262020 | Mob : +91 88865 50506;

Email : info@instrukart.com | www.instrukart.com

Head Office: #18, Street-1A, Czech Colony, Sanath Nagar, Hyderabad -500018, INDIA.

